

decoplast V30

decoplast Flaechen- und Fliesenspachtel

Synthetic resin modified cement-based joint filler on mineral and dispersion surfaces for interior and exterior use. Stays elastic, over paintable and weather resistant.

Instructions for use:

decoplast V30 is ideally suited for making good, smoothing, levelling and coating all mineral surfaces such as lime and cement based plaster, gypsum plaster, concrete, aerated concrete, clay tiles and on solid adhesive dispersion surfaces. The filled areas are easy to smooth off and felt. Not suitable for levelling out floors and for filling works on wood, metal, plastic or glass.

Technical Specification:

| | |
|---------------|--|
| Components: | Synthetic resin powder, Methyl cellulose, special cement |
| Density: | Approx. 0,9 g/cm ³ |
| pH-Value: | Approx. 12 |
| Mixing ratio: | 1 kg powder with 400 ml Water |
| Usage: | 1 kg powder for 1 m ² by 1 mm layer thickness |
| Working time: | Approx. 30 minutes (at 20°C) |
| Colour: | White |
| Smell: | Neutral |

Surface preparation:

The surface must be dry, firm and free of release agents (dust, formwork oil, etc.). Remove old wallpapers and flaking coats of paint with *decotric Wallpaper Remover* removes loose plaster. Prime highly absorbent, sanding and chalking surfaces with *decotric Deeply Penetrating Primer – Solvent Free*.

Application:

Pour clean, cold water into a container and sprinkle in *decoplast V30*. Stir vigorously until a smooth, lump-free mortar results. The stirred filler compound can be used for up to 30 min and can immediately be applied in wished thickness. Unevenness can be damply smoothed or felted after approx 90 min. Do not carry out subsequent works (painting, gluing, drilling, etc.) until the filled area has completely dried. Do not flout or coat with mineral paints. Work processes as wallpapering or applying of synthetic resin based plaster are possible to make as usual when the filled area has completely dried. It is not necessary to prime the surface for subsequent wallpapering and painting works.

Always observe the paint and adhesive manufacturer's instructions for the pre-treatment of cement bound surfaces

Do not use if the surface and/or room temperature is less than +5° C. Higher temperatures than +20° C lead to a shorter setting time and lower temperatures lead to longer setting time.

Clean tools in water immediately after use.

Storage:

Store in a dry place! Keep the containers tightly sealed!

Sizes:

| | |
|-----------------|-----------|
| 750 g paper box | 033101000 |
| 5 kg paper bag | 033102001 |
| 15 kg paper bag | 033107001 |
| 25 kg paper bag | 033104001 |